



## Spartan Chemical Company, Inc.

1110 Spartan Drive, Maumee OH 43537

Phone: (800) 537-8990

www.spartanchemical.com

### Training Information

**Market Segment:**

Building Service Contractors, Education, Food Processing\_Agricultural, General Manufacturing, Government, Healthcare, Lodging\_Hospitality, Other, Retail

**Title:**

#### HOW TO TOP SCRUB A FLOOR

Check If Applicable:  Rx Procedure  None  
 Cleancheck Procedure

**Tools & Materials Needed:**

- A. 175 rpm single disk machine
- B. Blue or green pads
- C. Two mops
- D. Two buckets with wringers
- E. Wet/dry vacuum
- F. "Wet floor" signs
- G. Gloves and goggles

**Products:**

- 1. All purpose cleaner

**Procedures:**

I. Purpose of Top Scrubbing

- A. To remove heavy dirt, stains and scuff marks.
- B. Preliminary step to recoating or high speed buffing the floor to restore original finish appearance.

II. Procedure for Top Scrubbing

- A. Put on gloves and goggles.
- B. Fill both buckets with water.
- C. In one bucket, mix the all purpose cleaner according to manufacturer's directions.
- D. Place "Wet floor" signs at each entrance.
- E. Apply diluted cleaning solution to a 10 foot by 10 foot area of the floor with a mop.
- F. Scrub the wet floor with the single disk and pad.
- G. Pick up the scrubbed solution with the wet/dry vacuum.
- H. Rinse the floor just scrubbed with clear water and a rinse mop.

- I. Repeat on another 10 foot by 10 foot area until the entire floor has been top scrubbed.
- J. Wipe baseboard down to clean up any splashes from scrubbing.
- K. Rinse entire floor with a fresh bucket of clear water.
- L. Allow floor to dry.
- M. Top scrubbing does not restore the floor's original luster.
  - 1. Floor is now ready to recoat or high speed buff.
  - 2. Refer to those sections for instructions on how to proceed.