



Spartan Chemical Company, Inc.

1110 Spartan Drive, Maumee OH 43537

Phone: (800) 537-8990

www.spartanchemical.com

Training Information

Market Segment:

Building Service Contractors, Education, Food Processing_Agricultural, General Manufacturing, Government, Healthcare, Lodging_Hospitality, Other, Retail

Title:

HARD SURFACE STAIR CLEANING

Check If Applicable: Rx Procedure None
 Cleancheck Procedure

Tools & Materials Needed:

Goggles and Gloves
Sponges
Wet Floor Signs
All Purpose Cleaner Spray Bottle
Broom & Dust Pan
Putty Knife
Bucket & Wringer
Neutral Cleaner
Spray Bottle of Disinfectant
White Cloths

Procedures:

1. Place Wet Floor Signs at top and bottom of stairs. Check to see if any light bulbs are not working in the light fixture or "Exit" sign in the stairwell. If so, remove the cover and replace the bulbs. Clean cover and replace.
2. Starting at the top of the stairs, sweep stairs from the top to the bottom. Pick up loose debris with the broom and dust pan. Using the putty knife, scrape any gum or tar from the stairs as you sweep.
3. Put on personal protective equipment.
4. Using the spray bottle of disinfectant and a cloth, spray the cloth until wet and wash the hand rails. When the cloth becomes soiled, change the cloth.
5. Using the spray bottle and sponge, working from the top down, clean the risers, edges and corners.
6. Dip the mop in the bucket of neutral cleaner and wring out. Mop the stairs from the top down. When the stairs are dry, remove Wet Floor signs.
7. Rinse the mop. Clean the bucket and wringer and store in the usual manner.