



## Spartan Chemical Company, Inc.

1110 Spartan Drive, Maumee OH 43537

Phone: (800) 537-8990

www.spartanchemical.com

### Training Information

**Market Segment:**

Building Service Contractors, Education, Food Processing\_Agricultural, General Manufacturing, Government, Healthcare, Lodging\_Hospitality, Other, Retail

**Title:**

#### HOW TO HIGH SPEED BUFF

Check If Applicable:  Rx Procedure  None  
 Cleancheck Procedure

**Tools & Materials Needed:**

- A. High speed machine
- B. Appropriate pads
- C. Dust mop

**Products:**

- 1. Dust mop/dust cloth treatment
- 2. Gloves and personal protective equipment

**Procedures:**

- I. Purpose of High Speed Buffing
  - A. Improve the attractiveness of floors by increasing the gloss.
- II. Procedure for High Speed Buffing
  - A. Dust mop, then damp mop the floor, following procedures.
  - B. Allow floor to dry.
  - C. Place appropriate pad on machine.
  - D. Do not use an extension cord when working with high speed machines.
    - 1. Machine will operate more efficiently.
    - 2. Machine will have a longer life.
  - E. Start high speed buffing next to the baseboard. Work away from the electric outlet to keep from tangling the cord.
  - F. When you come to the end of your pass:

1. Raise the machine pad off the floor before turning.
  2. When you have turned around, lower the machine pad gently.
    - a. This will prevent damage to the floor.
- G. After high speed buffing the entire area, dust mop the floor using a treated dust mop.
- H. Remove the pad from the machine. Wash out and hang to dry.
- I. Wrap up cord and store machine for future use.
1. Do not allow machine to rest on pad drive holder.