

Spartan Chemical Company, Inc.

1110 Spartan Drive, Maumee OH 43537 Phone: (800) 537-8990 www.spartanchemical.com

Training Information

Market Segment:

Building Service Contractors, Education, Food Processing_Agricultural, General Manufacturing, Government, Healthcare, Lodging_Hospitality, Other, Retail **Title:**

FLOORS HOW TO USE PREVENTIVE MAINTENANCE

Check If Applicable:	Rx ProcedureCleancheck Procedure	○ None

Products:

- 1. Dust mop/dust cloth treatment
- 2. Liquid floor cleaner
- 3. Spraybuff
- 4. Floor finish

Procedures:

- I. Tools and Materials Needed -- See chart at end
 - A. Walk off mats, exterior and interior
 - B. Dust mop, treated with dust mop/dust cloth treatment
 - C. Mop heads, frames and handles
 - D. Buckets and wringers
 - E. Liners for the buckets
 - F. 175 rpm single disk & blue or green pads
 - G. High speed machine and pads
 - H. Wet/dry vac, if available
 - I. Trigger sprayer
 - J. Clean rags
 - K. Floor hazard signs
 - L. Gloves and glasses
- II. Purpose of Preventative Maintenance
 - A. Stripping is time consuming and unpleasant.
 - B. Preventive measures can lengthen the time between stripping.
- III. Progressive Steps in Floor Maintenance
 - A. Entrance mats

- B. Dust mopping
- C. Damp mopping
 - 1. Damp mopping only
 - 2. Damp mopping followed by spray buffing
 - 3. Damp mopping followed by high speed restore
- D. Top Scrubbing
 - 1. Followed by high speed buffing
 - 2. Followed by a recoat of floor finish

For instructions and information about each of these floor maintenance procedures, look through the rest of this section.

EQUIPMENT LIST FOR FLOOR CARE PREVENTIVE MAINTENANCE

Product	Dust Mop	Damp Mop	Spray-b uff	Restore	Top Scrub	High Speed	Recoat
	X	X	X	X	X		X
Dust mop	X			X		X	
Mop #1		X			X		
#1 Bucket/ Wringer		X			X		
Mop #2		X			X		
#2 Bucket/ Wringer		X			X		
Mop #3				X			X
#3 Bucket/ Wringer				X			X
Liner				X			X
Trigger Sprayer			X				
175 rpm w/ blue or green pad					X		
Wet/dry vacuum					X		

High speed & pad		X	X		X	
Step off towel				X		X
Floor hazard sign	X	X	X	X		X