



Spartan Chemical Company, Inc.

1110 Spartan Drive, Maumee OH 43537

Phone: (800) 537-8990

www.spartanchemical.com

Training Information

Market Segment:

Building Service Contractors, Education, Food Processing_Agricultural, General Manufacturing, Government, Healthcare, Lodging_Hospitality, Other, Retail

Title:

PROCEDURE FOR CLEANING A NEGLECTED QUARRY TILE FLOOR

Check If Applicable: Rx Procedure None
 Cleancheck Procedure

Tools & Materials Needed:

1. Cleaner
2. Two mop buckets and wringers
3. Two mops
4. A stiff deck brush or push broom
5. Gloves and goggles

Procedures:

Put on gloves and goggles

1. Fill one bucket with cleaner solution, fill the other with clean water.
2. Section the floor into 6' sections.
3. Apply cleaner to the floor liberally.
4. Let stand for 5 minutes.
5. Scrub the section with a deck brush.
6. Wring out the rinse mop as dry as possible and pick up the dirty solution.
7. Rinse the mop in the clean water and wring it out.
8. Change the rinse water frequently.
9. Repeat this procedure until the entire floor is clean.