

# Spartan Chemical Company, Inc.

1110 Spartan Drive, Maumee OH 43537 Phone: (800) 537-8990 www.spartanchemical.com

## **Training Information**

### Market Segment:

Building Service Contractors, Education, Food Processing\_Agricultural, General Manufacturing, Government, Healthcare, Lodging\_Hospitality, Other, Retail

Title:

## PROCEDURE TO SEAL THE GROUT IN QUARRY TILE

Check If Applicable:   Rx Procedure  Cleancheck Procedure	● None
○ Cleancheck Procedul	i e

#### **Procedures:**

SUGGESTION: Do a test area to make sure the customer is happy with the look that is achieved since, the concrete seal can only be removed with paint or vanish stripper.

#### PROCEDURE:

Put on the proper personal protective equipment.

- 1. Clean the floor well using SNB-l30 or SC-200, using either a push broom or a Zim-grit of Nylo-grit brush on the bottom of a floor machine. Rinse the floor thoroughly to remove all the alkalinity.
- 2. If the grout remains discolored, use Concrete Prep which will actually etch the grout and remove any stains. Again rinse the floor thoroughly. By this I mean flood rinsing the floor at least two times.
- 3. When the floor is dry, pour Spartan penetrating solvent based concrete seal on a spot. Using a Waterwand Squeegee (made by Unger), squeegee the excess Concrete Seal over the entire area. You will find that this will pull the seal off the flat surface and push it into the grouted areas of the floor. Allow the seal to dry.
- 4. Using a black stripping pad on the bottom of a single disc floor machine and run it over the floor to remove any excess Concrete Seal that might have been left on the flat surface.